



PARTS LIST:


A-1PC




B-1PC




C-2PCS




D-2PCS




E-1PC




F-2PCS




G-1PC




H-1PC



I-1PC



J-2PCS




K-1PC



L-2PCS




M-2PCS



N-1PC



O-32PCS




P-32PCS




Q-16PCS





R-2PCS













S-2PCS






T-1PC




HARDWARE LIST:


1 -1PC 	2 -24PCS 	3 -16PCS 
4 -12PCS 	5 -61PCS 	6 -61PCS 
7 -8PCS 	8 -1PC 	9 -4PCS 
10 -9PCS 		




step 4




step 6





step 5





step 7





step 8



step 10



step 9



step 11

